

DEC 7 1959

COMPANY NAME THE PERKIN-ELMER CORPORATION		ENGINEERING STUDY <input type="checkbox"/>		CHANGE PROPOSAL <input checked="" type="checkbox"/>		Proposal No. P-E-10				
DATE December 2, 1959		AFFECTS: WSPO <input checked="" type="checkbox"/>		PROJECT <input type="checkbox"/>						
NAME OF MAJOR COMPONENT Tracker MK II		PART OR LOWEST SUBASSEMBLY PE 501-1564		PART NO. & MODEL OR TYPE						
TITLE OF PROPOSAL: Modify Scan Cam										
NATURE OF PROPOSAL: Replace the present scan cam with an improved cam. This can be a field modification. This item was originally proposed as item 9 of schedule "B", ECP P-E-5. Due to the urgency of this change, we suggest that it be done as a field modification on a production list basis under Contract HF-CT-695.										
REASON FOR PROPOSAL: A study of tracker skipping and scan failures indicates that the scan latch is returning too soon and is hitting components of the ratchet-dog assembly. The results are skipping and mid-scan failures. To delay the return of the scan latch, a new scan cam has been designed and lab. tested. The new cam delays the scan latch until the ratchet-dog assembly has moved out of position.										
E S		ESTIMATED COST AND TIME INVOLVED: N/C ADDITIONAL FUNDING REQUIRED:								
C P		ESTIMATED COST FOR KITS OR PARTS: 40 @ \$10.00 ea. ADDITIONAL FUNDING REQUIRED:								
ITEMS AFFECTED BY PROPOSAL:										
Safety <input type="checkbox"/>	Mission Effectiveness <input type="checkbox"/>	Performance <input checked="" type="checkbox"/>	Operating Procedure <input type="checkbox"/>	Interchangeability <input type="checkbox"/>	Weight or Weight & Balance <input type="checkbox"/>	Tools & Support Equipment <input type="checkbox"/>	Maintenance Procedure <input type="checkbox"/>	Service Life <input type="checkbox"/>	Flight Manual <input type="checkbox"/>	Maintenance Manual <input type="checkbox"/>
EST. MAN/HRS. REQ'D. TO ACCOMPLISH CHANGE IN FIELD								two hours		
SOURCE OF PARTS FOR KIT Contractor					AVAILABILITY 6 WEEKS AFTER APPROVAL			STATINTL		
DISPOSITION OF SPARES AFFECTED Scrap - part cannot be modified.										
INITIATED BY: Contractor					APPROVED: WSPO					

STATINTL

Approved For Release 2002/06/14 : CIA-RDP71B00697R001600050094-4

Approved For Release 2002/06/14 : CIA-RDP71B00697R001600050094-4